SIL

SERVICE INFORMATION LETTER   22_003C

Stoneridge

Recipients :	**HALE Nord Bohemia, s.r.o.**
Release date :	23.3.2022
Update Purpose :	
Object :	Optimo Software - historie

Objective: present a complete list of the new features and improvements in relation to each Optimo² software versions.

Main functionalities timeline:

- 1C SRE (Connekt) & VDO (4.0) calibration, from 5.1

- Optimo1-only GNSS Test, SW 5.2

- Enter SRE Module serial on the VDO4.0, from 5.4

- Configure VDO3.0, from 5.4

- Last Optimo1 SW version, SW 5.8

- Configure VDO4.0, from 6.0

- DSRC Read Cable, from 6.0-3808

- EFAS calibration, from 6.1

- Enter EFAS Module serial on the Connekt, from 6.2

- Restructured Read & Modify Menu, from 6.2

- User Generated Configurations – UGC, from 6.2

- Stop controlling VDO 1381-# in 1381CS, from 6.2

- New Wireless interface Revision 5.3.2 to address quick accelerations. from 6.3

- Next calibration date automatically updated, from 6.4

- Configure 900588RH, from 6.4

Detailed functionalities History table:

SW 6.4	6.4.x000.4014	**SIL22_005**
		14/3/2022

Release purpose: Next calibration date is now automatically updated whenever the k/w factor is updated through Read & Modify or through any Calibration method.
Support configuring new Connekt version 900588RH.

MKIII	Updated and reorganize some Tiles based on customer feedback.
MKIII	Added "Border Crossing Driver Assistance"
MKIII	Add Chassis Id to VDO4.0 and 4.0e in Read & Modify
MKIII	Enabling LINX tablet finger sweep on all Optimo applications.
SE5000CS	UGC: Secured the new User Generated Configuration functionality by removing the Calibration parameters from the UGC files. In particular, odometer will not be saved and will not be pushed to the target tachographs.
SE5000CS	It has been udpated to allow configuring the new Rev. H Connekt.
Workshop Settings	Added the "Sondino Kit" option for Italy.
Workshop Settings	Added Greek language with English keyboard.

SW 6.3	6.3.x000.4000	**SIL22_002**
		14/3/2022

Release purpose: New Wireless interface Revision 5.3.2 to address quick accelerations. Add WiFi5 support

MKIII	Secure *Remote download card writing*: can only be deactivated.
MKIII	Resolved VRN question-mark padding and non-English character set, and its impact on DSRC RTM Testing.
MKIII	1314 & 1319: Restored *Service delay* parameter.
MKIII	1319 & EGK100: Restored access on new Read & Modify menu.
Tachoswap	Add *Remote download on A-CAN* on 7.6.

SW 6.2	6.2.x000.3961		**SIL21_006B**
			29/10/2021
Release purpose: New Read & Modify Tiles menu, User Generated Configurations			
MKIII	New Read & Modify structure for a quicker and easier access to the parameters. See TSG011		
MKIII	Intellic DSRC Module: add capability to enter the module serial number, for both CONNEKT and VDO4.0 tachographs.		
SE5000CS	New function to create and share User Generated Configurations. See TSG010.		
CS1381	Removed VDO part number verification. Optimo only discriminates Universal vs OEM and 1B versus 1C.		
CS1381	Add new configurations.		
Workshop Settings	Slovenian, Serbian and Croatian special language characters can now be programmed into the tachograph for the VRN.		
Workshop Settings	Auto-handling of Unique Pan/Channel: Optimo² now resets PAN/ID to specific values as entered before software upgrading.		
Workshop Settings	Italy: Added the 9600 RBT option.		

SW 6.1	6.1.x000.3876		**SIL21_002**
			31/05/2021
Release purpose: New Connekt version 900588RG			
MKIII	Add new L factor entry via Tyre Radius or Tyre height.		
MKIII	Add control of new Optional CAN Messages 3: GNSS VP1, VP2, VDS.		
MKIII	Add new OEM part numbers, accessible only from the Optimo used to configure the tachograph. If not, error x0041.		
MKIII	Add new parameters for 900588RG.		
MKIII	Set all Digital bench tests to 70 seconds at 180km/h, to trigger OVERSPEED.		
MKIII	Remove the unpopulated GNSS details when connected to a 900588RA.		
MKII	Add a decimal for the speed shown for all the tests.		
MKIII	1381 & EFAS: Fixed the MKIII > Read & Modify x00FF error when exiting the Read & Modify after changing a parameter.		
MKIII	Italy: fixed error when trying to set time & date parameters or doing clock test with our Connekt.		
MKIII	Add Slovenia in the language option list, but special characters for VRN not supported yet		
SE5000CS	Add new variant RG35 and RG36. Add new and updated configurations for RB, RD and RG AM tachographs.		
CS1381	Add new VDO 3.0 and 4.0 universal part numbers.		
Sensor test	Removed unused icons.		
Camera	Add new features to the "Video capture" software.		
Software	Update Eula to incorporate the transfer of project responsibility to Tallinn.		

SW 6.0	6.0.x000.3808	SIL20_006B & SIL20_007 15/07/2020 & 21/12/2020

Release purpose: Capability to calibrate the new Intellic EFAS 1C tachograph

MKIII	Add occurrences for VDO DTC Codes.
MKIII	Add new DSRC CANbus test: read the Stoneridge DSRC module over the truck CANbus with a new cable.
MKIII	Add sensor serial number on Read & Modify.
MKIII	Add three new settings for Remote download parameters, SCANIA specific.
MKIII	Add GNSS Dilution of Precision values.
MKIII	Add EFAS 1C.
SE5000CS	Add New "Factory settings" configurations.
CS1381	Add VDO4.0.
Product Manual	Updates to the English manual, especially MKIII section, and removal of all references to Optimo1.
Workshop Settings	Add Serbian/Serbia in the language and country option list. Add Luxembourg in country option list with 3 languages. Add Slovenia in country option list, with English language.
Camera	Add Camera control to take pictures. Select "rear camera" and a resolution.
Software	Add Google Chrome as an alternative to Internet explorer. Removal of the *application sheet, cross reference* and *Fixed DSRC Test*.

SW 5.8	5.8.x000.3694	SIL19_017E 23/12/2019

Release purpose: Add control of Sleep Mode.

MKIII	Bench test increase from 60 to 70 seconds for the 180 km/h test in France/Italy/Holland.
MKIII	1000 meters test Improvements.
MKIII	Add control of Sleep Mode. Add control of Optional CAN Messages #3: allows turning on TCO3 messages for DDS on latest IVECO's Dashboard.
DSRC Test	DSRC testing and serial number entry improvements.
SE5000CS	Add "OEM part number" button on 7.6 Configuration Station.
Sensor test	New Optimo² cable reference 7000-240 is released for the Kitas2 & Kitas2+ testing. The 7000-239 cable is now dedicated to the Kitas4 and Lesikar testing.
Wireless Photocell Test	New Application for verifying Optimo-Wireless Photocell Connection.
Windows Calculator	For calculation.
Snipping Tool	For screen capture.

SW 5.4	5.4.x000.3627		SIL19_012B
			19/08/2019

Release purpose: Enter Stoneridge DSRC Module serial number in VDO4.0

MKIII	Add capability to enter the Stoneridge DSRC Module serial number into the VDO4.0 VU.
MKIII	Add control of Centralized Language parameter (MAN).
SE5000CS	Add 1C configurations based on the 1Bs. Add "OEM part number" button.
CS1381	Add capability to configure VDO3.0
Sensor test	On Optimo1 this is limited to Kitas2+. For Kitas4 sensors the workshops must use the reference cable procedure.

SW 5.3	5.3.x000.3586		SIL19_009C
			22/05/2019

Release purpose: Add capability to configure VDO 4.0 for the Stoneridge DSRC module.

MKIII	Add capability to configure the VDO4.0 for SRE DSRC Module
GNSS Test	Manually entered co-ordinates are now saved in the GNSS App
DSRC Test	To improve program launch responsiveness
SE5000CS	Add SE5000_Connekt to the SE5000CS

SW 5.1	5.1.x000.3563		SIL19_003B
			01/03/2019

Release purpose: Add 1C capability for SE5000_8 and VDO 4.0

MKIII	SRE & VDO 1C Calibration including 1C Seals
MKIII	MKIII cannot be used before entering a unique activation key
GNSS Test	New application for all 1C tachographs
DSRC Test	New application for all 1C tachographs